



TOA Canada Corporation

6150 Kennedy Road, Unit 3
Mississauga, Ontario L5T 2J4
Telephone: (905) 564-3570
Fax: (905) 564-3569

March 08, 2011

Subject: UHF Wireless Microphone System Changes

Effective March 31, 2011 TOA Canada Corporation will no longer be selling the **A01**, **B01** and **C01** band UHF Wireless Frequencies. This change is based on the decision by industry Canada:

<http://www.ic.gc.ca/eic/site/smt-gst.nsf/eng/sf09777.html>

TOA Canada is currently offering allowable frequencies that may be used in the **E01** (668 – 698 MHz, UHF) and **F01** (636 – 666 MHz, UHF) frequency bands.

Please note:

- For those users of the TOA 4000/5000 Series UHF wireless products in the **A01** band, the first 7 frequencies, 0-6, are still allowed as they fall between 692.125 to 696.475
- No **B01** frequencies are allowed
- The allowable 8 frequencies for the **C01** bands are channels 8 to F, 806.625 to 828.750
- For those users of the TOA Trantec S5.5 series, there are 10 frequencies in Band 7 that are available between 692.200 to 697.775 MHz

When ordering UHF Wireless products, care must be taken to ensure products ordered are of the correct frequency. Unlike frequency bands will not work together. When replacing either a microphone or receiver, they must be replaced in pairs so that their frequency bands match. It is advised to check the frequency band for all pieces in the system before ordering the replacement units.

TOA wireless microphone systems frequency band determination can be found in the model name, such as WM-5200 **E01**. The **E01** indicates the band that is used for these particular wireless microphones. The new and allowable TOA frequency designators may be **E01** and/or **F01**.

When ordering products for existing installations, please make sure that frequency band designators are indicated on the purchase order. As an example, a system using the WT-5810 **E01** receiver needs a new



TOA Canada Corporation

6150 Kennedy Road, Unit 3
Mississauga, Ontario L5T 2J4
Telephone: (905) 564-3570
Fax: (905) 564-3569

microphone. When ordering the new microphone, you would indicate the model number and the suffix **E01**. This will ensure that the receiver and microphone will work together.

UHF Wireless Replacement/Selection Guide (i.e. WM-5220 E01)

Product Code	Frequency Band	Replacement Frequency Band
200/300 Series – UHF Wireless Microphone System		
WS-200, WS-300, WS-300H	A01, B01	Discontinued Product Line
4000/5000 Series – UHF Wireless Microphone System		
WM-4200	A01	Discontinued Product
WM-4210	A01, B01, C01	Discontinued Product
WM-5220, WM-5270	A01, B01, C01	E01, F01
WM-5320, WM-5320A, WM-5320H	A01, B01, C01	E01, F01
WS-5200, WS-5300, WS-5300H	A01, B01, C01	E01, F01
WT-5800, WT-5805, WT-5810, WTU-4800	A01, B01, C01	E01, F01
S5.5 Series – UHF Wireless Microphone System Kits		
S5.5-HD-QA1S	A01	F01 (new product code S5.5-HD-QF1S)
S5.5-L-A1S	A01	F01 (new product code S5.5-L-QF1S)

TOA Canada Corporation carries a 2 channel IR Frequency Wireless Microphone System in addition to the UHF Wireless product lines. Visit our website for more information:

www.TOAcanda.com/products/wireless_microphones/ir_wireless_system.html

TOA Canada regrets any inconvenience this government decision may cause you and your customers.

Please visit www.TOAcanda.com/products/wireless_microphones.html for updates or more information on TOA's Wireless Products.

Thank you for being a loyal TOA customer and please don't hesitate to contact us if you have any comments or questions by calling TOA Technical Services 1-800-263-7639, Monday through Friday from 8:30am to 5:00pm EST or via email at: technicalsupport@toacanda.com

Sincerely,

TOA Canada Corporation Management

www.TOAcanda.com

1-800-263-7639 or 905-564-3570